

## ABSTRACT

Impurities are added to a conductor layer in a semiconductor process to prevent formation of void spaces and encourage complete filling of contacts. The impurities reduce the melting point and surface tension of a conductor layer, thereby improving  
5 filling characteristics during a reflow step. The impurities may be added at any time during the process, including during conductor deposition and/or reflow.

AUGUST 2000 BY SPARTAN